




City of Corning

Building Inspector

530-824-7027

SINGLE VAN ACCESSIBLE PARKING STALL AND SIGNAGE



NOTE: The example shown is for a Van Accessible stall. A typical accessible stall has all the same elements except the accessible aisle width is only required to be 5'.